


|  <b>IECEX Facility<br/>Assessment Report</b> |  |                           |
|---|--|---------------------------|
| <b>FAR Reference Number</b>   | NL/DEK/FAR11.0020/05   | <b>Status</b> Current     |
| <b>Issuing ExCB</b>   | DEK - DEKRA Certification B.V.   |                           |
| <b>FAR Free Reference Number</b>  | 219794200  |                           |
| <b>Date of Issue</b>  | <b>Audit date:</b>   | <b>Valid Until</b>        |
| 2017-06-12  | 2017-01-16   | 2020-01-16                |
| <b>Site audited</b>   | <b>Service Facility</b>  | <b>Country / Location</b> |
| Elektromotoren Emmen B.V.<br>W. Schoutenstraat 13<br>7825 VV Emmen  | Elektromotoren Emmen B.V.<br>W. Schoutenstraat 13<br>7825 VV Emmen   | The Netherlands           |
| <b>Detail of change</b>   | Reassessment performed and closed with positive result.  |                           |
| <b>Type of Work Covered by Service Facility</b>   | Repair and overhaul of Ex d, Ex e, Ex n, Ex t motors, transformers and generators.<br>Repair and overhaul of non-electrical equipment, mainly pumps, gearboxes and ventilators, with types of protection c and k |                           |
| <b>Related FARs</b>   | NL/DEK/FAR11.0020/05<br>NL/DEK/FAR11.0020/04<br>NL/DEK/FAR11.0020/03<br>NL/DEK/FAR11.0020/02<br>NL/DEK/FAR11.0020/01<br>NL/DEK/FAR11.0020/00   |                           |
| <b>Related IECEX Service Facility Certificates</b>  |  |                           |
| <b>Comment</b>  |  |                           |